



K32006 1/32 Spitfire Mk.Vb (Early)

The legendary Supermarine "Spitfire" is undoubtedly one of the most famous, and perhaps the most beautiful, aircraft of all time. Designed from 1934 under the guidance of Supermarine Aviation Works' chief designer Reginald Mitchell, Joseph Smith and "Alf" Faddy, the prototype first flew on 5 March 1936. The Supermarine built, 1030hp Rolls-Royce Merlin II/III powered, 8 Browning .303" machine gun armed, Spitfire Mk.I entered service from mid-May 1938. The rear fuselage was adorned with raised rivets for ease of construction while the main planes and front of the fuselage were flush riveted, puttied/filler primed and sanded smooth for improved performance. Numerous improvements were introduced throughout production. Some Mk.I were armed with 2 Hispano 20mm cannons which proved to be so unreliable that they were withdrawn from service in early September 1940. The problems were solved later that year, at which time it was reintroduced with an additional 4 Browning .303" guns and designated the Spitfire Mk.Ib ("B" wing), at which time the 8 Browning .303" gun armed aircraft was re-designated the Mk.Ia ("A" wing).

The Castle Bromwich Aircraft Factory (CBAF) built 1150hp Rolls-Royce Merlin XII powered Spitfire Mk.IIa and Mk.IIb featured many of the later Mk.Ia improvements although the key difference was the new engine which had a Coffman (explosive) cartridge starting system.

A 1390hp Rolls-Royce Merlin XX powered Spitfire Mk.III prototype had been in development since January 1940 which incorporated numerous improvements introduced throughout Mk.I/II production as well as many new innovations. In early 1941 an urgent need for improved performance saw the installation of the 1440hp Rolls-Royce Merlin 45 into approximately 365 internally strengthened Mk.Ia/IIa & Mk.Ib/IIb airframes thereby creating the stop-gap Mk.Va and Mk.Vb.

Early production Mk.Vb (as featured in this model) completed from early-1941 incorporated Mk.I/II airframe improvements introduced up to that time including constant speed DeHavilland & Rotol propellers, a carb intake ice/snow guard, fireproof bulkhead, deletion of the 47gal fuel gauge in the instrument panel, engine driven undercarriage controls, windscreen de-icing, Martin-Baker hood release (jettison) system, composite seat, pilot's armour plating, IFF Mk.II, a single parachute landing flare chute, electrical test door in the port wing fillet, raised rivet wireless and accumulator doors, Plessey flare device, and reinforced tailwheel strut. They also featured the improved "B" type wing, metal skinned ailerons, improved cannon shell ejection chutes, symmetrical/double-bulged and early asymmetric underwing cannon fairings, two-cell radiator, and an improved oil cooler design.

Mid production Mk.Vb completed from mid-1941 saw the introduction of additional types of DeHavilland and Rotol propellers, more efficient "fishtail" exhaust manifolds, tyres with concentric side-wall rings, armour under the seat and an emergency exit crowbar. Later production Mk.Vb saw the introduction of a 24 volt voltage regulator behind the pilot's headrest, rearranged gun heating and oxygen systems, wheel covers, external "slipper" fuel tanks, balloon hoods, internal windscreen armoured glass, a square reflector gun sight Mk.II, clipped wingtips, tropical air intake filters, and deletion of the landing lights, parachute flare and pilot's headrest. Very late serving aircraft could be found with multi-ejector exhaust manifolds, bomb carriers, and elevators with increased balance areas. Some of these modifications were retrofitted to earlier aircraft. A Mk.Vc was put into production from early 1942 and introduced the "C" wing, with modified undercarriage geometry, which could be armed with up to 4 Hispano 20mm cannons or 8 Browning .303" guns, although it was usually fitted with 2 cannons and 4 Browning guns.

Numerous additional engine, airframe and armament improvements were made to the Spitfire before production ceased in 1948, by which time over 22000 had been produced in 2-dozen variants with the most notable being the 1030hp Mk.I, 1470hp Mk.V, 1720hp Mk.IX, 2035hp Mk.XIV, the photo-reconnaissance Mk.XI and the navalised Seafire Mk.III.

Early production Mk.Vb featured the colours and finishing details of their respective airframe manufacturers. The interior areas were primed with light grey before being painted aluminium, except for the cockpit between frames 8 & 11 which appear to have been painted with grey-green (Supermarine), different from the green seen on early and mid-production Mk.I/Ia, and very pale grey-green (CBAF). Major internal components supplied by sub-contractors could be delivered in various shades of grey-green or aluminium or even black.

Upper surfaces were initially painted Dark Earth and Dark Green in varying shades applied with hard (Supermarine) and soft (CBAF) demarcation lines in the A pattern. The undersides (including the wheel wells, undercarriage struts and wheel hubs) were finished with "Sky Type S". Although Night (black) was reintroduced for the underside of the port wing from late November 1940 until late April 1941, no Mk.Vb appear to have been finished this way at the factory, although Mk.Vb converted from earlier production Mk.Ib would have had Night applied at the units, before being repainted again with Sky Type S. Spitfire sub-assemblies were usually supplied pre-painted so a single aircraft could exhibit a variety of shades, and sometimes the camouflage pattern would not match perfectly from one sub-assembly/component to the next. Early production Mk.Vb serving after mid-August 1941 would have received the new "Day Fighter" camouflage scheme with Ocean Grey (or mixed grey) applied over the previous Dark Earth, and Medium Sea Grey applied over the previous "Sky Type S" undersides. These new colours could be brush painted or sprayed on depending on what equipment was available at the time.

Additionally, extensive weathering and re-painting (hand brushed as well as sprayed) also helped ensure that a wide variety of tonal differences could be seen. While we have tried our best with our paint suggestions, there is no doubt many will disagree with us. Which is OK.

Richard Alexander 2025

Wingspan:	Length:	Max Weight:	Max Speed:	
36ft 10in (11.23m)	29ft 11in (9.12m)	6700 lb (3039kg)	370mph (595kph)	
No Manufactured (Mk. Vb):	Production:	Engine:	Ceiling:	Armament:
3950 approx. (including conversions)	March 1941 to May 1942	1440hp Rolls-Royce Merlin 45	37700ft (11500m)	2x 20mm Hispano-Suiza cannons & 4x .303" (7.7mm) Browning machine guns
References:				
Supermarine factory engineering drawings – Pilot's Notes Spitfire Va, Vb & Vc Aircraft..., Air Publication 1565E - Supermarine Spitfire Mk V in Europe and North Africa, Wingleader Photo Archive #6 2021 – Supermarine Spitfire Mk V, Wojtek Matusiak, MMP 2004 – The Spitfire Story, Alfred Price, Jane's Publishing 1982 – Spitfire The History, Eric B. Morgan and Edward Shacklady, Key Publishing 1987 – Spitfire notes (various), Edgar Brooks – The Imperial War Museums – Australian War Memorial Museum – Mark Postlethwaite – www.nationalarchives.gov.uk – www.airhistory.org.uk – Andy Hosking – Private Collections.				
The following additionally provided photos for publication in this instruction booklet, for which we are incredibly grateful: ww2images.com – Air Force Museum of New Zealand – Private Collectors (various).				

K32006 1/32 Spitfire Mk.Vb (Early)

Warning: Choking hazard. Keep small parts and plastic bags away from children. Use glue/cement and paint in a well-ventilated area. Always wear protective eyewear when cutting and protective mask when painting, gluing and sanding. Do not breathe in dust. Beware of sharp edges.

Assembly: Read all the instructions carefully 3 times before starting assembly. Yes, even if you are very experienced. Use glue/cement intended for plastic models. Assemble metal and resin parts (if included) with cyanoacrylate (CA) or epoxy glue. Select a marking option before starting assembly and note the optional parts required on your instructions.



Optional Detail can be ignored if you don't feel comfortable doing it. It is not 100% necessary to complete your model. For rigging long control cables and aerial wire we recommend stretchy elastic type material like "EZ Line" etc and thin metal or plastic for short control cables and rods etc.

Painting: Only use paint designed and suitable for plastic model kits. If in doubt, test on scrap plastic from this model before using.

Decals: Avoid painting unnecessary and harsh colour demarcation lines under white decals. Cut out each decal only as required. Soak in warm water for around 15 seconds. Help avoid "silvering" by not over-soaking and washing off the decal glue. Slide decal off backing paper on to smooth painted surface of model and move into position using a fine paint brush and/or tweezers. It can be helpful to apply a small drop of water mixed with PVA glue to the area where decals are being applied to make them easier to maneuver into position and help avoid silvering. If necessary, use decal setting and solvent solutions but only after first testing on spare decals from this model. Alternatively, carefully use a hair dryer or very hot water (applied with a brush) to soften and conform decals to surface details. Do not overheat because you will damage your model.

Hints & Tips: Please visit www.kotare-models.com for any additional hints and tips to help you get the best result from your model.

1	Construction Step	25	Decal		Paint Colour		Attention	i	Optional Display
A23	Part Number		Remove		Drill		Choose		Glue for metal
ABC	Options		Do Not Cement		Fill		Optional Detail		Other Side


	Colour*	Tamiya	Humbrol	SMS	FS/BS**
a	Interior grey-green – semi-gloss	XF71	78	PL100	FS34227
b	Interior grey-green (pale) – semi-gloss	XF76	240	PL94	FS34424
c	Brass – metallic	X31	54	PMT13	–
d	Night – matt	XF85	67(x1)+33(x1)	PL229	FS37070/BS642
e	Aluminium paint – metallic	XF16	27001	PMT09	–
f	Gun metal – semi gloss	X10	27004	PMT08	–
g	Rubber – matt	XF69	66	PL216	–
h	Beige linen – matt	XF57	121	PL226	FS30475
i	Dark Earth (dark) – matt	XF52(x1)+XF90(x1)	29	PL228	FS30118/BS450
j	Dark Earth (pale) – matt	XF49(x1)+XF92(x1)	26	–	–
k	Dark Green (dark) – matt	XF81	116	PL227	FS34079/BS241
l	Dark Green (pale) – matt	XF89	117	–	FS34159
m	White – matt	XF2	34	PL27	–
n	Medium sea grey – matt	XF83	165	PL108	–
o	Sky Type S (duck egg blueish green) – matt	XF21	90	PL124	FS34558
p	Red – gloss	X7	19	PL49	FS11400
q	Yellow – matt	XF3(x10) + X6(x1)	24	PL162	FS33538
r	Dark red brown – semi gloss	XF79	70	PL15	–
s	Frosted opaque lens – semi gloss	XF16(x1)+XF2(x1)	11(x1)+34(x1)	–	–
u	Chrome – metallic	X11	27002	CHM01	–
v	Black – matt	XF1	33	PL178	–
w	Light grey – matt	XF25	87	PL27	FS35237
x	Clear orange – gloss	X26	1322	PL22	–
y	Dark Green – gloss	X5	3	PL50	–
z1	Sky (pale duck egg blue) – matt	XF2(x4) + XF23(x1)	34(x4) + 65(x1)	–	FS35550
z2	Mixed grey – matt	XF83(x7) + XF1(x1)	–	–	–
z3	Ocean Grey – matt	XF82	106	PL86	–

* Colours matched to the best of our ability.


** FS = Federal Standard. BS = British Standard.

Note: Apply clear varnish to achieve the desired gloss, semi-gloss and matt finish.


A parts




G parts




H parts




C parts




D1/D2 parts




E parts




K1/K2 parts



 = Not used




Decals



PAINT GUIDE

Colours shown are approximate only





See also pages 8 & 9.

1 COCKPIT


PAINT GUIDE

Colours illustrated are approximate only.




Instrument panel detail from June 1942 CBAF built Spitfire Mk Vb EP287 photographed in late February 1943. Note the spade grip [K2] with dual cannon/gun selector, Mk.Ia instrument flying panel [G15], single fuel gauge [122], and empty pressure gauge hole.

? = a AB b C




2 COCKPIT CONTINUED




3 COCKPIT CONTINUED

? = a AB b C




Engine driven undercarriage control unit K6 from a late production Spitfire Mk.Ia.





IFF Mk.II A.R.I 5000

G3 w ? g




d & e A29 Drill holes in for more detail




Frame 13 & wireless box



A29 e Mounting for aerial mast





Remove front parachute flare chute



CBAF built mid-production Spitfire Mk.Vb AB870 OU-Z "Hawkes Bay I (Dannevirke)" was completed and delivered to 485 Squadron in early August 1941 where it is seen here sometime the following month. Note the unusual combination of a blunt Rotol RX5/3 spinner with RX5/10 propeller blades.

PAINT GUIDE



Colours shown are approximate only




PAINT GUIDE

Colours shown are approximate only

Colours shown are approximate only






Supermarine Eastleigh built Spitfire Mk.Vb W3333 "Hendon Pegasus" is from the same production order as **B** and is seen here shortly after completion in early June 1941 before its cannon armament was installed and wearing Dark Earth, Dark Green camouflage upper surfaces with "Sky Type S" undersides. Note the pristine factory applied stencils, IFF Mk.II aerial wires running from the tip of the horizontal tailplane to the side of the fuselage, upward firing Plessey flare device hole, old-style TR.9D aerial mast, and imperfectly painted fuselage roundel. Also note the high underside camouflage demarcation line that is not evident on the rear fuselage of W3328 **B**, indicating that the upper surface colours of W3328 were almost certainly extended further downwards when it was repainted after mid-August 1941.




RIGGING GUIDE



Rigging material not supplied



4 COCKPIT COMPLETED




5 FUSELAGE INTERIOR




Downward firing Plessey flare device hole details from Spitfire Mk.Vb R6923 **A**. This was introduced into production from mid-1940.

Drill hole for downward firing Plessey recognition flare device.


6 FUSELAGE INTERIOR



Accumulator door with raised rivets **H10** from Spitfire Mk.Vb W3433.




Starboard engine cowling from June 1941 Supermarine Eastleigh built Spitfire Mk.Vb W3433. Note the header tank vent in the lower position introduced for the Merlin 45 engine, the round hole for the hand crank (with health and safety warning instructions **58**) and the generally poor fit of the cowlings. The fastener alignment markings would quickly wear off and/or be overpainted later in service.







Starboard engine cowling from an early production 1440hp Merlin 45 powered CBAF built Spitfire Mk.Vb of 72 Squadron in July/August 1941. This Mk.Vb is almost certainly one of the 78 or so Mk.II completed as Mk.Vb, or 11 or so converted to Mk.Vb. Note the redundant teardrop fairing designed to clear the Coffman starter drive housing of the 1150hp Merlin XII engine of the Spitfire Mk.IIa/b. Also note the electrical engine starter plug and the key-hole for the hand crank.

7 FUSELAGE EXTERIOR






The Plessey flare device was moved to this upward firing position during production in early 1941. This is Spitfire Mk.Vb W3433.






Engine cowling (port) E10

Top cowling





Early style of CBAF door stencils. Note the orientation of the stencils 54, 55, & 56.

Small air intake scoop detail H2 from Spitfire Mk.Vb R6923 A.




Cockpit door (closed) option


Crowbar mounts were introduced into production in mid-1941. The crowbar was not always fitted.




8 TAILPLANE




Starboard tailplane detail. Note the data plaque and the lightening holes in the outer rib of the tailplane.



A19



Port elevator detail from Supermarine Chattis Hill built Spitfire Mk.Vb W3373 photographed in October 1941. Note the hinge cutouts, subtle rib-stitching and lack of scalloping on the tightly doped fabric covered surface. Also note the lack of pre (and post) shading effects either side of the ribs.



Elevators


E13

1st


A19 Fairing

2nd

Remove tabs to adjust position



Supermarine Eastleigh built Spitfire Mk.Vb R6882 "City of Leeds" PR-Z was from the same Mk.I production order as **A** and was retained for training and developmental duties. In February 1941 a Merlin 45 engine was fitted and it was delivered to 92 Squadron early the following month before going on to 609 Squadron, where it is seen here in late August 1941. Note the Rotol RX5/14 spinner with wooden propeller blades, triple ejector exhaust manifolds, ice guard **H1**, camera hole in the wing fillet and the rear-view mirror **A15**. Red self-adhesive patches and rubber sheaths have been applied over the gun ports and cannon muzzles respectively.



Supermarine Eastleigh built Spitfire Mk. Vb W3433 "Progress II" is from the same production order as **B** and was photographed here shortly after completion in late June 1941. The Dark Earth and Dark Green camouflage is an interesting mix of soft edge on the main fuselage and hard edge on the sub-contractor supplied rudder, fuel tank plating and engine cowlings. The "Sky Type S" undersides have been applied with a soft edge, and quite high up the rear fuselage. Note the pristine factory applied stencils, IFF Mk.II aerial wires running from the tip of the horizontal tailplane to the side of the fuselage, old style TR.9D aerial mast and wire and the weighted appearance of the tyres. Also note the non-concentric yellow ring of the fuselage roundel. The pale Sky band around the rear of the fuselage and spinner would have been painted on at 38 MU (Maintenance Unit) where it was delivered on 26 June 1941 before it went into service with 616 Squadron a few days later.

9 MAIN PLANES

Gun heating hot
air outlet fairing
(starboard)


D3

D7 Main planes
underside

K16 Carb intake
fairing

D4 Gun heating hot air
outlet fairing (port)

Very early



Early/mid



A K28

Cannon magazine
fairing panel
(starboard)

BC D8

K7 Gun heating
ducts



Very early thin
symmetrical
underside port
cannon magazine
fairing K27 from
Spitfire Mk.Vb
R6923 A.

A K27


Cannon magazine
fairing panel (port)

BC D9

Very early



Early/mid




Very early thin symmetrical underside starboard cannon magazine fairing with small additional fairing K28 from Spitfire Mk.Vb R6923 A.




Early/mid wide asymmetrical underside starboard cannon magazine fairing D8 from Spitfire Mk.Vb EN821.



Early/mid wide asymmetrical underside port cannon magazine fairing D9 from Spitfire Mk.Vb EN821.





10 MAIN PLANES EXTERIOR




Camera gun port detail from Spitfire Mk.Vb BM202. Note the ill-fitting cowling panels.

11 RADIATOR & OIL COOLER




Oil cooler with full rear fairing as seen on an unidentified 54 Squadron Spitfire Mk.Va photographed in mid-1941. The lower, fully round, oil cooler opening was introduced to improve the cooling required for the more powerful Merlin 45 engine of the Mk.V.




Oil cooler with trimmed rear fairing as seen on Spitfire Mk.Vb R6923.


12 MAIN PLANES & FUSELAGE ASSEMBLY





Oil tank and bottom cowlings E8 from mid-production Spitfire Mk.Vb BM202. Note the imperfect fitting panels and generally rough finish.



13 UNDERCARRIAGE





Undercarriage detail from late production Supermarine built Spitfire Mk.Vb AB344 photographed in January 1942. Note the 90 gallon "slipper" fuel tank and how the wheel, strut and door are painted the underside colour. The small flange at the bottom of the undercarriage door is a feature of Supermarine/Eastleigh built aircraft.




Undercarriage detail from an unidentified CBAF built 332 Squadron Spitfire Mk.Vb. Note how the wheel, strut and door are all painted the underside colour. The wide flange at the bottom of the undercarriage door is a feature mainly noted on CBAF built aircraft.

14 DETAILS



Rotol RX5/14 wooden propeller detail from an unidentified 65 Squadron CBAF built Spitfire Mk.IIa.






Pobjoy Aeromotor & Aircraft built rudder from Supermarine Eastleigh built Spitfire Mk.Vb W3433 photographed in late June 1941. Note the stenciling, the lightening holes in the outer rib of the tailplane and the rear light fairing.




DeHavilland DH.5/39 propeller detail from Spitfire Mk.Vb W3328

B



20mm Hispano cannon muzzle detail from Spitfire Mk.Vb BM229. The tip was usually covered with a red fabric or rubber sheath.




Port triple ejector nozzle outlet exhaust manifold **A6** & **A7** detail from an unidentified 19 Squadron late production Spitfire Mk.Ia. These exhaust manifolds were supplied by Rolls-Royce and were made from Inconel, an alloy that does not rust (even after 4 decades under a Calais beach)! The same style of exhaust was used on early production Mk.Va/b. Note the weld lines and stencil markings **40**, **42** & **44**.

15 CANOPY



Paint inside canopy frame **r** to represent Linatex red rubber seals. Paint exterior canopy frames **k** **?** **l**

i Hood closed & door closed option



Canopy hood detail from Spitfire Mk.Vb W3433. Note the Sutton harness retaining wire and voltage regulator **A18** in the aft window, the Martin Baker hood release (jettison) bars, rear-view mirror, GM.2 reflector gunsight and thickness of the external armoured windscreen.



Cockpit door without crowbar brackets, the same type fitted to R6923 **A**. See also page 13.



Brackets were introduced in mid-1941 and crowbars shortly thereafter. Spitfire Mk.Vb W3257 was completed in May 1941 and is seen here 3 months later still without a crowbar.

i ? ii Hood open options

Windscreen with de-icing system

C17


C4 Aft window

Cockpit door (open)


ii A42

Note front


Crowbar mounts were introduced into production in mid-1941. Crowbar possibly fitted to **BC**.



C15 Hood, Martin Baker release (jettison) type





Note position



AB ? RIGGING


IFF Mk.II aerial wires (rigging material not supplied).



Supermarine Chattis Hill built
Spitfire Mk.Vb W3373, October 1941.




Early production Spitfire Mk.Vb W3373 is from the same production order as **B** but was completed at Supermarine's Chattis Hill factory in June 1941. It is reportedly seen here in October 1941, almost certainly after being extensively refurbished at Scottish Aviation. Spitfire Mk.Vb W3373 would have initially been finished in Dark Earth and Dark Green with "Sky Type S" undersides but is seen here in the "Day Fighter Scheme" introduced in mid-August 1941 of Dark Green and Ocean Grey (or "mixed grey") with Medium Sea Grey undersides, all applied with soft edges here. Note the CBAF style large flange undercarriage doors and lack of armament. In typical Spitfire fashion, the undercarriage struts, doors, wheels and wheel wells are painted in the underside colour. Note that some non-Supermarine factory airframe stencils appear to have been applied by Scottish Aviation.



Note the DeHavilland DH.5/39 propeller and spinner with Night backing plate, exhaust manifolds, CBAF style panel line in the engine top cowl and the small air scoop by the windscreen. The film and/or filter type has caused the yellow and red of the markings to appear very dark, and possibly caused the Ocean Grey to appear very pale, unless a lighter "mixed grey" was used due to the lack of available Ocean Grey. Unusually, for this timeframe, the canopy is not yet fitted with the Martin Baker hood release (jettison) system. Also note the clear fairing over the upward facing identification lamp.



Spitfire Mk.Vb W3328 initially served with 609 Squadron before going to Scottish Aviation in late July 1941. It then went on to serve with 154, 315, 349 and 303 Squadrons before being retired to 51 OTU and finally struck off in September 1945. Note the weighted tyres, TR.1133 aerial mast (without external aerial wire), and the IFF Mk.II wires running from the tips of the horizontal tailplanes to the fuselage roundel, which has been painted slightly further forward than is typical.



Spitfire Mk.Vb R6923 **A** was one of the few Mk.I to have 20mm Hispano cannon armed wings fitted (without .303" Browning guns). After briefly serving in 19 Squadron later in 1940, it was withdrawn and an improved Hispano cannon and Browning gun armed "B wing" was fitted and Spitfire Mk.Ib R6923 was delivered to 92 Squadron late that year. In April 1941 a 1440hp Merlin 45 engine was fitted and it became Spitfire Mk.Vb R6923 before being returned to 92 Squadron where it is seen here on 16 May 1941. Note how numerous repaints have eliminated the factory applied wing walk stencil markings, how the Dark Green near the inner leading edges is much darker than on the rest of the wings, and the overall well-worn and patchy finish.




Spitfire Mk.Vb R6923 is from the 4th production order placed with Supermarine in October 1939 for 450 late production 1030hp Mk.I with 8 Browning gun armament (numbers R6595 to R7350). It was one of 26 aircraft from this order to have 20mm Hispano cannon armed wings fitted (without Browning guns) and was delivered to 19 Squadron in late July 1940 before being withdrawn in early September 1940 to fix the hopelessly malfunctioning cannon armament. It then had a modified Hispano cannon and Browning gun armed "B wing" fitted, with improved ducting for the empty 20mm shells & disintegrating link and went on to serve with 92 Squadron from at least 2 December 1940. In early April 1941, Spitfire Mk.Ib R6923 was sent away to have a 1440hp Merlin 45 engine fitted and returned a couple of weeks later as Spitfire Mk.Vb R6923. During its 6 months of service with 92 Squadron, it was flown by numerous pilots but most commonly by AR Wright, although it was being flown by WG Aston when it was shot down on 21 June 1941. Aston bailed out and was rescued from the sea but just 5 days later he was forced to bail out again, although this time he was captured and made POW.



When R6923 was initially completed in late July 1940, the upper surfaces would have been painted Dark Earth and Dark Green in the B camouflage scheme with "Sky Type S" undersides (including the undercarriage struts, doors, wheels and wheel wells), all applied with a hard edge. Sometime after very late November the port wing underside was painted Night (black), a yellow ring applied around the port underside roundel, and the spinner and band around the rear fuselage were painted Sky (usually a paler bluish colour than the underside "Sky Type S"). In April 1941 the port wing underside was again repainted "Sky Type S". All surfaces exhibit extensive weathering and examples of paint touch up repairs, resulting in at least 2 markedly different shades of Dark Green and the elimination of all the factory applied airframe stencils.

Allan Richard Wright was born in Devon on 12 February 1911 and joined the RAF as a cadet in 1936 and served with 92 Squadron from late October 1939, initially flying Bristol Blenheims before the Squadron converted to Spitfires in March 1940. Wright remained with 92 Squadron and was credited with 5 victories, 3 shared, 3 probables and 1 damaged before being shot down and wounded in late September 1940. He was credited with another victory on 6 December 1940 and remained with the Squadron until July 1941 when he was posted to 59 OTU (Operational Training Unit). Wright then served in HQ and instructing roles until he was posted to 29 Squadron in March 1943 where he was credited with his final victory in early April 1943.

He spent the rest of the war in training and instructing roles and eventually retired as a Group Captain in February 1967. Wright was 95 when he died on 16 September 2015.



Port side view of Spitfire Mk.Vb R6923 QJ-S photographed in flight. This photo, and other photos here of R6923, were taken on 16 May 1941 when it was being flown by Wright. Note the DH.5/39 propeller, oil cooler and TR.1133 aerial mast.



Spitfire Mk.Vb R6923. Note the heavily weathered finish and patchwork repainted areas of Dark Green. Also note the "East India Squadron" unit marking ⑥ painted on the fuel tank cover and illegible name, possibly "Sara" ③, under the windscreen. Although in this image the gun port covers appear very pale, other images confirm they are almost certainly dark red.



Spitfire Mk.Vb R6923 with the angle of the sunlight exacerbating the uneven surface features of the wings.



Yet another view of Spitfire Mk.Vb R6923 showing the heavily weathered and patchy finish of the wings.

KOTARE



KOTARE

KOTARE



KOTARE

KOTARE

KOTARE

KOTARE





Spitfire Mk.Vb W3328 photographed to document the "slightly damaged" starboard wing following combat on 21 October 1941. The film and/or filter type has caused the yellow ring around the fuselage roundel to appear the same tone as the blue. Note the dark appearance of the upward facing signal lamp [C2], different tones of Dark Green and mixed grey, and the poorly fitting engine cowlings,



The "slightly damaged" starboard wing tip of Spitfire Mk.Vb W3328. Note the imperfectly painted yellow stripe on the leading edge.



Edward Jaworski emphasizes the size of the hole in the wingtip. Unlike the rest of the wing, much of the internal wing tip structure was wooden, with most of the skin attached with screws.




Edward Jaworski (top right) describes the recent action that resulted in his "slightly damaged" wing. Note the lighter blue repainted area of the roundel, pale "mixed grey" (?) camouflage, partially overpainted wing walkway marking, and the ill-fitting Browning gun cover.

C Spitfire Mk.Vb HL-C, FA Hill & E Dalrymple, 308th FS, 31st FG, 8th Air Force USAAF, Tangmere, & Kenley, July-August 1942



Although the serial number is not confirmed, Spitfire Mk.Vb HL-C appears to be from the production order placed with CBAF in April 1939 for 1000 Spitfire Mk.II (numbers P7280 to P8799) and is one of the 90 or so completed as (or converted to) 1440hp Mk.Vb between early June to late July 1941. When initially completed, the upper surfaces would have been painted Dark Earth and Dark Green in the A camouflage scheme with "Sky Type S" undersides (including the undercarriage struts, doors, wheels and wheel wells) with soft edges. After mid-August 1941 the Dark Earth would have been overpainted with Ocean Grey or, more likely, an iteration of "mixed grey" (exact shade unknown) and the undersides repainted Medium Sea Grey. The wheel well, wheels, insides of the undercarriage doors and struts would have remained in their original "Sky Type S". It appears to have been extensively repainted again before it entered service with the 308th FS (Fighter Squadron) around July 1942. The RAF roundels have been overpainted with USAAF cocarde (star) markings, those on the wings being reduced in size (port upper & starboard lower) or overpainted completely (starboard upper and port lower).




308th FS Spitfire Mk.Vb HL-C photographed in flight with Dalrymple at the controls in July 1942. Note the Roto RX5/14 propeller spinner, lack of pilot's head rest and height of the fuselage cocarde compared with the letter "C". Also note the pale linen(?) cannon muzzle covers. (E Dalrymple via Ventura Publications)




It is quite likely that all wing walkway markings and stencils had been overpainted before being handed over to the USAAF.

Frank Ackerman Hill joined the US Army Air Corps in 1939 and qualified to be a pilot late the following year. He initially flew with the 308th FS before commanding the 309th FS and then the 31st FG (Fighter Group). He had been credited with 7 victories by the time he returned to the USA in late 1943. He remained in the Air Force in various command roles until he retired in 1969. Hill was 92 years old when he died in January 2012.


Edwin Dalrymple was born in January 1916 and flew Spitfires with the 308th FS. He appears to have been credited with 2 victories. Edwin remained in the Air Force after the war and appears to have retired as a Lt. Colonel before going on to serve in the FBI for many years. Dalrymple was 90 years old when he died in February 2006.



Spitfire Mk.Vb HL-C is seen here at Kenley around July-August 1942. Note the heavily stained "mixed grey" or Ocean Grey areas, lack of airframe stencils and the engine side cowling [K22] with the keyhole style crank handle hole and small teardrop fairing at the front. (FA Hill via Ventura Publications)




CBAF built Spitfire Mk.Vb BM642 is a mid-production aircraft completed in April 1942 but is included here to show the extensively weathered and patched wing surfaces after less than 10 months' service. Also note the non-slip area at the rear of the port wing root (66).




John Aitken of the 2nd Fighter Squadron, 52nd Fighter Group USAAF with his unidentified Supermarine built early production Spitfire Mk.Vb in late October 1942. Note the ice guard (H15), triple ejector exhaust manifolds, covered cannon muzzle, and heavy weathering

Below: Port wing cannon magazine fairing detail from a CBAF built mid-production Spitfire Mk.Vb from 332 Squadron believed to have been photographed in April 1942. Note the ill-fitting panels and repainted camouflage finish.



A

KOTARE



A nice view of Spitfire Mk.Vb R6923 showing the patchy finish of the repeatedly repainted underside. Note the unusually dark lower surface of the radiator fairing and the extensive oil staining (which ends abruptly as it re-enters the fuselage through the parachute flare hatch). The dark ring around the port wing roundel appears to be the remnants of the overpainted yellow ring which had been applied when the port wing was painted black.

Product Design – Darren Mildenhall

Born and raised in Wellington, New Zealand, Darren graduated with a major in Industrial Design from the School of Design. During the degree he developed a passion for form and the aesthetic appeal of a product and how to utilise CAD software to realise and develop a concept. When not designing scale model aircraft, Darren enjoys spending time with his wife and two young children and renovating their 1920s house.

Profile Art – Ronny Bar

A former rock musician, Ronny Bar has had a lifelong interest in aircraft since growing up near the El Palomar Air Force Base in Buenos Aires. He started drawing and building models of aircraft soon after a flight in a T-34 Mentor trainer at the age of 10, Spitfires and Messerschmitt first... Camels and Fokkers later. After retiring from the R'n'R scene he returned to his early interest of aviation artwork. Visit Ronny's Facebook page at <https://www.facebook.com/pages/RONNY-BAR-Aircraft-Profiles/166538664131>.

Proprietor – Mark Robson

Mark is a practising veterinary specialist in the field of small animal internal medicine and has had a lifelong interest in scale modelling and aviation since his dad bought him his first Airfix kit when he was just 5 years old. Mark is excited to share his love of models with modellers through Kotare and hopes that they will get as much enjoyment out of these models as he does. Mark is a committed dad to two grown children and loves beaches, craft beer and music.

Decal Art – Malcolm Laird

Malcolm has been in the scale model industry since 1981, first as Falcon vacform models (www.falconmodels.co.nz, sold to Tore Martin in 1985) and from then on as Ventura Publications which produced decals and short run injection moulded kits. He still produces his line of Ventura decals and a range of soft cover aviation books mainly with a Kiwi flavour. Outside work he suffers the dual afflictions of restoring old Kawasaki motorcycles and trying to paint impressionist landscapes, with 'mixed' results so far. Visit Malcolm's web site at www.venturapublications.com

Box Art – Darryl Legg

Darryl was born in Cape Town, South Africa in 1975 and his interest in aircraft and passion for art inspired him from an early age. He has been a full-time professional artist since he was 20 years old and is considered to be one of the world's finest aviation artists. He currently lives in the Karoo town of Middelburg. Find out more about Darryl's work at www.aviationartsa.com

K32006 Product Manager – Richard Alexander

Richard is an award-winning modeller and has been in the model and hobby trade since the early 1990s. Richard retains his enthusiasm for ensuring your models are highly detailed and accurate while remaining as simple and enjoyable to build as possible, no matter what your skill level. If you have any questions about building your Kotare model, comments, requests or suggestions, Richard is contactable at richard@kotare-models.com.

Historic photos courtesy of ww2images.com, Air Force Museum of New Zealand and private collectors (unless credited otherwise).


Thank you for your support.

www.kotare-models.com



Spitfire Mk.Vb, 31st Fighter Group, 308th Fighter Squadron, 8th Air Force, USAAF, July-August 1942. By Darryl Legg

K32006	Spitfire Mk.Vb (Early)	Qty
00K32001A	A parts	1
00K32002C	C parts	1
00K32006D1/D2	D parts	1
00K32001E	E parts	1
00K32002G	G Parts	1
00K32002H	H Parts	1
00K32006K1/K2	K Parts	1
10K32006	Instructions	1
20K32006	Decals	1



High quality 3Dprint resin detail set sold separately for this model featuring details not possible with injection moulding.

If you have damaged or missing parts, please contact your Kotare retailer or email help@kotare-models.com for assistance.

www.kotare-models.com

© 2025 Kotare Models, PO Box 56141, Mt Eden, Auckland 1466, New Zealand.
All rights reserved. Designed in New Zealand – Manufactured in China

3 COCKPIT CONTINUED CORRECTION

